

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 1. Overview of location taken facing east.



Photo 2. Trash, weeds, and stained soil at pump jack.



Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 3. Stained soil on location.



Photo 4. Stained soil and noxious weeds.



Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 5. Incomplete battery sign.



Photo 6. Stained soil.

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 7. Stained soil.



Photo 8. No label on tank. Stained soil at base.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 9. Stained soil.



Photo 10. No label on tank. Stained soil at base.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 316744



Photo 11. Sediment migration on access road.



Photo 12. Sediment migration on access road.

