

**Inspection Photos**  
**Location Name: Gnat Hill 1-29**  
**Location ID: 425278**



**Photo 1. Overview of location taken facing southeast.**



**Photo 2. Stained soil at pump jack exhaust.**

**Inspection Photos**  
**Location Name: Gnat Hill 1-29**  
**Location ID: 425278**



**Photo 3. Stained soil at wellhead.**



**Photo 4. Trash/debris at wellhead.**

Inspection Photos  
Location Name: Gnat Hill 1-29  
Location ID: 425278



Photo 5. No calibration documentation in meter run.



Photo 6. Stained soil from apparent spill.

Inspection Photos  
Location Name: Gnat Hill 1-29  
Location ID: 425278



Photo 7. Stained soil from apparent spill.



Photo 8. Stained soil from apparent spill.