

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06905**  
**Date: 6/29/2020**




Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing, largely with crested wheatgrass and western wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of dense Russian knapweeds within the western project area. Approximately 2000 individuals observed.



Photo 5. View of the reference area, comprised of irrigated grass field with tall fescue and clovers.