

Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 1 – Former tank battery and pit location south of and between 121-10563 and 10560



Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 2 – View W



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 3 – View E from west end of location



Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 4 –



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 5 – View S

Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



06.29.2020

Photo # 6 –



Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 7 –



Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



06.29.2020

Photo # 8 –



Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 9 – View E at former pit area

Location Name: – PADCO – Rem #14006  
Inspection Date: 06/29/2020



Photo # 10 –

