

Inspection Photos

6/12/2020

Operator: CAERUS WASHCO LLC #86610

Location ID: 335016

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: CAERUS WASHCO LLC #86610

Location ID: 335016



Photo 1: Photo taken from the southeast corner of the Location, facing north. Photos 1-3 provide an overview of the Location from north, northeast to east. Photos show Location has not been recontoured/reclaimed; SOVR has been approved to not contour pad. Photo also shows areas of the slopes on the southeast corner that remain bare and at risk of erosion.



Photo 2: See comments under photo 1. Photo also shows areas of the slopes on the southeast corner that remain bare and at risk of erosion.

Inspection Photos

Operator Name: CAERUS WASHCO LLC #86610

Location ID: 335016



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the south end of the Location, facing west. Photos 4-7 provide an overview of the Location from west, northwest, northeast to east.

Inspection Photos

Operator Name: CAERUS WASHCO LLC #86610

Location ID: 335016



Photo 5: See comments under photo 4. Photo also show areas of the pad where additional revegetation activities appear to have been conducted. Records suggest work was conducted in 2018.



Photo 6: See comments under photo 4 and 5.

Inspection Photos

Operator Name: CAERUS WASHCO LLC #86610

Location ID: 335016



Photo 7: See comments under photo 4.



Photo 8: Photo taken from the southeast corner of the Location, facing west. Photos 8-10 provide an overview of the Location from west, northwest to north. See comments under photo 1.

Inspection Photos

Operator Name: CAERUS WASHCO LLC #86610

Location ID: 335016



Photo 9: See comments under photo 8.



Photo 10: See comments under photo 8.

Inspection Photos

Operator Name: CAERUS WASHCO LLC #86610

Location ID: 335016



Photo 11: Photo taken from the north end of the pad, facing east. Photos 11-14 provide an overview of the Location from east, southeast, southwest to west.



Photo 12: See comments under photo 11.

Inspection Photos
Operator Name: CAERUS WASHCO LLC #86610
Location ID: 335016



Photo 13: See comments under photo 11.



Photo 14: See comments under photo 11.

Inspection Photos

Operator Name: CAERUS WASHCO LLC #86610

Location ID: 335016



Photo 15: Photo taken from the northwest corner of the Location, facing east. Photos 15-16 provide an overview of the Location from west to south.



Photo 16: See comments under photo 15.

Inspection Photos
Operator Name: CAERUS WASHCO LLC #86610
Location ID: 335016



Photo 17: Photo taken from the access road, facing east. Photo show reclamation of the access road is in process.