

Location Name: – Ward and Son Operating - Loc ID 317229
Inspection Date: 06/29/2020




Photo # 1 –

Location Name: – Ward and Son Operating - Loc ID 317229
Inspection Date: 06/29/2020



Photo # 2 – Open former oil skim pit excavation, no Form 27 has been provided for this project, produced water tank being undermined

Location Name: – Ward and Son Operating - Loc ID 317229

Inspection Date: 06/29/2020



Photo # 3 – Former oil skim pit cover and impacted soil stockpile remain on site.