

Inspection Photos

API#045-06795

Operator: DOE

Inspection Number: 692402244

Inspection Date: 5/27/20





Photo#1:

View NW into Location from access road and out of location to SE along access road.

May 27, 2020



Photo#2:

View over sediment deposition flowing from NE corner of site.

May 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

DOE PA 2-W-26 API#045-06795



Photo#3:
Fence is in disrepair.



Photo#4:
Fence is in disrepair.

May 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

DOE PA 2-W-26 API#045-06795



Photo#5:
Erosion & sediment migration.




Photo#6:
Erosion & sediment migration.

May 27, 2020



Photo#7:
Erosion & sediment migration.



Photo#8:
Erosion & sediment migration.

May 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

DOE PA 2-W-26 API#045-06795