

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2020

Submitted Date:

06/30/2020

Document Number:

688000457

FIELD INSPECTION FORM

Loc ID 317229 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 94300
Name of Operator: WARD & SON* ALFRED
Address: P O BOX 737
City: OGALLALLA State: NE Zip: 69153

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107553	PIT	AC			-	STATE 4	EI

General Comment:

Environmental inspection related to open spills, former oil skim pit excavation (open) with no approved Form 27.

Inspected Facilities

Facility ID: 107553 Type: PIT API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Active Spill IDs 446492, 456489, 454306

Corrective Action: Provide the information required per COA on the above referenced spills. FI 688000196 indicates a CA date of 10/12/2018 for submittal of disposal manifests and soil sample analytical data for a minimum of four soil samples. Contact NE EPS with any questions regarding this CA. Date: 10/12/2018

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Open former oil skim pit excavation and soil stockpile on site.

Corrective Action: Submit Form 27 for oil skim pit closure. Include soil disposal manifests and soil sample analytical data and soil sample location map as applicable. Date: 03/06/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000458	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5188058