

Inspection Photos

Loc#418417

Operator: Ursa

Inspection Number: 692402334

Inspection Date: 6/18/20





Photo#1:
Overview of Location from entry.

June 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Porter B Pad Loc#418417



Photo#2:
Scotch thistle scattered on portions of Location.

June 18, 2020



Photo#3:

View of Cut slope; inserts close up of weedy areas of vegetation on Cut slope.

June 18, 2020



Photo#4:
Area of concern on Fill slope.

Photo#5:
Area of concern on Fill slope.

June 18, 2020