

Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 1. Overview of location taken facing east.




Photo 2. Stained soil at pump jack base.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 3. Stained soil at wellhead.



Photo 4. Stained soil.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 5. Lube oil stored without containment.



Photo 6. Sediment migration down access road.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 7. Sediment migration down access road.



Photo 8. Stained soil on location.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 9. No containment.



Photo 10. Stained soil on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources