

Inspection Photos
Location Name: Voloshin 3-25
Location ID: 432878



**Photo 1. Overview of location taken facing southeast.
Workover stored on location.**



Photo 2. Gauge hatches open.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Voloshin 3-25
Location ID: 432878



Photo 3. Tank stored without containment or labels.



Photo 4. Contents of tank in photo 3.



Inspection Photos
Location Name: Voloshin 3-25
Location ID: 432878



Photo 5. Equipment stored on location.



Photo 6. Noxious weeds on location.

