

Inspection Photos
Location Name: State of Colorado 1-16
Location ID: 316763



Photo 1. Overview of location taken facing northeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: State of Colorado 1-16
Location ID: 316763



Photo 2. Incomplete label.



Photo 3. Noxious weeds on location.



Inspection Photos
Location Name: State of Colorado 1-16
Location ID: 316763



Photo 4. Access road overgrown.



Photo 5. Access road overgrown.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources