

Inspection Photos
Location Name: Nichols 10-6 TB
Location ID: 425952



Photo 1 TB/signs

Photo 2 TB

Inspection Photos
Location Name: Nichols 10-6 TB
Location ID: 425952



Photo 3 Horizontal Heated Separators

Photo 4 ECD

Inspection Photos
Location Name: Nichols 10-6 TB
Location ID: 425952



Photo 5 Stained soil under east Horizontal Heated Separator

Photo 6 possible leak on Separator drain

Inspection Photos
Location Name: Nichols 10-6 TB
Location ID: 425952



Photo 9 Flow line

Photo 10 flow line

Inspection Photos
Location Name: Nichols 10-6 TB
Location ID: 425952



Photo 11 Gas Meter Run