

**Inspection Photos**  
**Location Name: Nichols Tank Battery 37N-31HZ**  
**Location ID: 429183**



**Photo 1 TB signs**



**Photo 2 TB**

**Inspection Photos**  
**Location Name: Nichols Tank Battery 37N-31HZ**  
**Location ID: 429183**



**Photo 3 LACT**



**Photo 4 ECDs**

**Inspection Photos**  
**Location Name: Nichols Tank Battery 37N-31HZ**  
**Location ID: 429183**



**Photo 5 VRU**



**Photo 6 electric panels**



**Inspection Photos**  
**Location Name: Nichols Tank Battery 37N-31HZ**  
**Location ID: 429183**



**Photo 7 Horizontal Heated Separators**



**Photo 8 Horizontal Heated Separators**

# Inspection Photos

Location Name: Nichols Tank Battery 37N-31HZ  
Location ID: 429183



Photo 9 Gas Meter Run




Photo 10 card inside of meter house, due for calibration.


**Location ID: 429183**



**Photo 12 card inside of meter house, current calibration.**

**Inspection Photos**  
**Location Name: Nichols Tank Battery 37N-31HZ**  
**Location ID: 429183**

**Location ID: 429183**



Colorado Oil & Gas Conservation Commission  
11183 Co Rd 39, Fort Lupton, CO 80621, USA  
40.16079, -104.70433, 48851ft, 322°  
07/01/2020 10:57:28

**Photo 14 card inside of meter house, due for calibration.**