

Inspection Photos

Location Name: Savage 8A-794 Pad and Flowline Releases
Location ID: 413476 & Spill/Release IDs: #456039 & #457002
Inspection Date: June 30, 2020



Photo #1 – View of wellheads and separators from the northeast.



Photo #2 – View of tank battery and pump houses from northwest.



Inspection Photos

Location Name: Savage 8A-794 Pad and Flowline Releases
Location ID: 413476 & Spill/Release IDs: #456039 & #457002
Inspection Date: June 30, 2020



Photo #3 – Well sign.



Photo #4 – Savage 34C-5 wellhead.



Inspection Photos

Location Name: Savage 8A-794 Pad and Flowline Releases
Location ID: 413476 & Spill/Release IDs: #456039 & #457002
Inspection Date: June 30, 2020



Photo #5 – View of day tanks and chemical pumps on west side of fenced wellhead area.



Photo #6 – View of separators from northwest. Photo depicts backfilled former excavation area for Remediation Projects #11661 and/or #11786.



Inspection Photos

Location Name: Savage 8A-794 Pad and Flowline Releases
Location ID: 413476 & Spill/Release IDs: #456039 & #457002
Inspection Date: June 30, 2020



Photo #7 – ECD located east of separators. Photo depicts backfilled former excavation area for Remediation Projects #11661 and/or #11786.



Photo #8 – View of area between separators and tank battery. Photo depicts backfilled former excavation area for Remediation Projects #11661 and/or #11786.



Inspection Photos

Location Name: Savage 8A-794 Pad and Flowline Releases
Location ID: 413476 & Spill/Release IDs: #456039 & #457002
Inspection Date: June 30, 2020



Photo #9 – Unused equipment (1/4" process pipe) located southeast of ECD. Photo depicts backfilled former excavation area for Remediation Projects #11661 and/or #11786.



Photo #10 – Overview of tank battery from southwest. Photo depicts backfilled former excavation area for Remediation Projects #11661 and/or #11786.



Inspection Photos

Location Name: Savage 8A-794 Pad and Flowline Releases
Location ID: 413476 & Spill/Release IDs: #456039 & #457002
Inspection Date: June 30, 2020



Photo #11 – Day tanks located southwest of pump house.



Photo #12 – View of pump houses from southwest.



Inspection Photos

Location Name: Savage 8A-794 Pad and Flowline Releases
Location ID: 413476 & Spill/Release IDs: #456039 & #457002
Inspection Date: June 30, 2020



Photo #13 – Localized accumulation of oil-stained soil southwest of tank battery.



Photo #14 – Open shed in southeast end of pad. Note 55-gallon drums slightly overhang cement foundation of shed. Operator was notified via phone of this issue on 7/3/2020.

