

# *Inspection Photos*

*Loc#323899*

*Operator: Terra*

*Inspection #: 692402337*

*Inspection Date: 6/23/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

June 23, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Terra McNary Loc#323899



Photo#2:  
East side Interim inundated with sediment.

June 23, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Terra McNary Loc#323899





Photo#3:

Sediment is migrating off pad ion East side, depositing into Interim areas.

June 23, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Terra McNary Loc#323899