



39.80717, -108.41294, 6708 6ft, 309°
07/01/2020 01:44:19 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

RG 31-8-398 API: 05-103-10622
Inspection: 700402240



39.80756, -108.4134, 6700.1ft, 353°
07/01/2020 01:42:10 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

RG 31-8-398 API: 05-103-10622
Inspection: 700402240



39.80783, -108.41306, 6689 6ft, 321°
07/01/2020 01:46:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

RG 31-8-398 API: 05-103-10622
Inspection: 700402240



39.80735, -108.41281, 6713.8ft, 278°
07/01/2020 01:45:03 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

RG 31-8-398 API: 05-103-10622
Inspection: 700402240



39.80804, -108.4132, 6694.1ft, 309°
07/01/2020 01:47:43 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank.

RG 31-8-398 API: 05-103-10622
Inspection: 700402240