



39.76411, -108.46767, 6951.4ft, 27°  
07/01/2020 02:52:57 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**South Sulphur 1**

**API: 05-103-05041**

**Inspection: 700402248**





39.7641, -108.46754, 6988.5ft, 173°  
07/01/2020 02:53:23 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Location.**

**South Sulphur 1**

**API: 05-103-05041**

**Inspection: 700402248**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Top of P&A marker. Gas leaking out ~  
1mm in diameter holes.**

**South Sulphur 1**

**API: 05-103-05041**

**Inspection: 700402248**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 4. P&A marker.

South Sulphur 1

API: 05-103-05041

Inspection: 700402248



