

Inspection Photos

Loc#335068

Operator: Terra

Inspection #: 692402340

Inspection Date: 6/23/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

June 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Terra Clough Loc#335068



Photo#2:

Sparse Vegetation on East side of site; insert of Cheat grass infested berm on South side. .

June 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Terra Clough Loc#335068



Photo#3
Unmarked Anchor.

June 23, 2020



Photo#4:
BMP needing maintenance.

Terra Clough Loc#335068



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources