

Inspection Photos

Loc#413476

Operator: Caerus

Inspection #: 692402350

Inspection Date: 6/30/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

June 30, 2020



Photo#2:
Cut Slope.

June 30, 2020



Photo#3:
Cut Slope.

Caerus Savage Loc#413476



Photo#4:
Fill slope Interim area.

June 30, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Fill slope Interim area and BMP.

Caerus Savage Loc#413476



Photo#4:
View over pad & remediation areas.



Photo#5:

June 30, 2020