

**Inspection Photos**  
**Location Name: Latham 14-12 Pad**  
**Location ID: 429825**



**Photo #1 Tank Battery**



**Photo #2 Pumping Units**

**Inspection Photos**  
**Location Name: Latham 14-12 Pad**  
**Location ID: 429825**



**Photo #3 Compressor, gas lift & Meter run**



**Photo #4 Separators & ECDs**

Inspection Photos  
Location Name: Latham 14-12 Pad  
Location ID: 429825



Photo #5 Trash



Photo #6 Trash

Inspection Photos  
Location Name: Latham 14-12 Pad  
Location ID: 429825



Colorado Oil and Gas Conservation Commission  
40.32038, -104.39237, 4515.1ft, 206°  
07/06/2020 11:08:16 AM

Photo #7 Oily waste



Colorado Oil and Gas Conservation Commission  
40.32096, -104.39755, 4578.4ft, 312°  
07/06/2020 11:45:06 AM

Photo #8 Stained soil

**Inspection Photos**  
**Location Name: Latham 14-12 Pad**  
**Location ID: 429825**



Colorado Oil and Gas Conservation Commission  
40.32095, -104.39752, 4578.7ft, 45°  
07/06/2020 11:45:15 AM

**Photo #9 Trash**



Colorado Oil and Gas Conservation Commission  
40.321, -104.39753, 4570.0ft, 282°  
07/06/2020 11:45:30 AM

**Photo #10 Unused Equipment**

**Inspection Photos**  
**Location Name: Latham 14-12 Pad**  
**Location ID: 429825**



Colorado Oil and Gas Conservation Commission  
40.32096, -104.39804, 4562.0ft, 350°  
07/06/2020 11:47:12 AM

**Photo #11 Unused cable**



Colorado Oil and Gas Conservation Commission  
40.32101, -104.39764, 4561.3ft, 207°  
07/06/2020 11:45:58 AM

**Photo #12 Unused equipment**

**Inspection Photos**  
**Location Name: Latham 14-12 Pad**  
**Location ID: 429825**



**Photo #13 Trash**

**Photo #14 Unused Equipment**

Inspection Photos  
Location Name: Latham 14-12 Pad  
Location ID: 429825



Photo #15 No Placard

Photo #16 No Placard

**Inspection Photos**  
**Location Name: Latham 14-12 Pad**  
**Location ID: 429825**



**Photo #17 Unused "tote" Equipment**