

Inspection Photos

API#045-06832

Operator: Caerus

Inspection #: 692402343

Inspection Date: 6/25/20





Photo#1:
Overview of Location to East.

June 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus PA Knight API#045-06832



Photo#2:
View along access road, up into Location.

June 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Patch of Russian Olive, B-List Noxious Weed.

Caerus PA Knight API#045-06832



Photo#4:
East side fill slope of access road, covered in old growth ruderal debris weeds.



Photo#5:

June 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus PA Knight API#045-06832