

Inspection Photos  
Location Name: Miller 23-17  
Location ID: 336436



Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Miller 23-17  
Location ID: 336436



Photo 3 TB signs


Photo 4 TB

# Inspection Photos

Location Name: Miller 23-17  
Location ID: 336436



Colorado Oil & Gas Conservation Commission  
9216 Co Rd 15, Longmont, CO 80504, USA  
40.13368, -104.92167, 4897.2ft, 89°  
07/06/2020 14:32:08



Colorado Oil & Gas Conservation Commission  
9216 Co Rd 15, Longmont, CO 80504, USA  
40.13369, -104.9216, 4906.6ft, 315°  
07/06/2020 14:32:33

**Photo 5 Gas Meter Run**

**Photo 6 Card inside meter house indicates current calibration**



**Inspection Photos**  
**Location Name: Miller 23-17**  
**Location ID: 336436**



**Photo 9 Horizontal Heated Separators, Flow lines**

**Photo 10 ECD**