

Inspection Photos
Location Name: Miller 2-4-17
Location ID: 330025



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Miller 2-4-17
Location ID: 330025




Photo 3 TB signs

Photo 4 TB

Inspection Photos
Location Name: Miller 2-4-17
Location ID: 330025



Colorado Oil & Gas Conservation Commission
 9216 Co Rd 15, Longmont, CO 80504, USA
 40.13368, -104.92167, 4897.2ft, 89°
 07/06/2020 14:32:08



Test Date	OP Size	Note	Sample Date	H ₂ S	Sample Date	H ₂ S	C	Gravity
5-29-16	1.125		5-29-16	1.0				
8-16-16	2.125	v	8-18-16	1.0				
11-28-16	1.125		1-20-17	1.0				
2-24-17	1.125		2-24-17	1.0				
5-15-17	1.125		5-15-17	1.0				
8-18-17	1.125		8-18-17	1.0				
11-2-17	1.125		11-2-17	1.0				
2-16-18	1.125	v	2-16-18	1.0				
5-24-18	1.125		5-24-18	1.0				
8-21-18	1.125		8-21-18	1.0				
2-24-19	1.500		2-24-19	1.0				

Colorado Oil & Gas Conservation Commission
 9216 Co Rd 15, Longmont, CO 80504, USA
 40.13369, -104.9216, 4906.6ft, 315°
 07/06/2020 14:32:33

Photo 5 Gas Meter Run

Photo 6 Card inside meter house indicates current calibration

Inspection Photos
Location Name: Miller 2-4-17
Location ID: 330025



Photo 9 Horizontal Heated Separators, Flow lines

Photo 10 ECD