

Inspection Photos

API: 071-08730

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/6/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08730 | Date: 7/6/2020

Inspection Photos



Photo 1. Facing southwest along the access road which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 7/6/2020

Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 7/6/2020

Inspection Photos



Photo 3. Facing southeast toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 7/6/2020

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 7/6/2020