

Inspection Photos

Operator: BP America
API: 067-09513
Date: 7/6/2020



Photo 1. View of the project area from the southwestern edge facing northward.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome, western wheatgrass, and crested wheatgrass. Russian knapweed infestation along the southern edge of the project area is partially treated. Approx. 500 individuals observed.



Photo 3. View of Russian knapweed that does not appear to be treated with herbicide.



Photo 4. View of the reference area, comprised of open pinyon and juniper woodland with black sage understory and a mix of native and non-native grasses and forbs such as smooth brome and Navajo tea.