



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Photo 1. Location.

M.B. Larson C9X25

API: 05-103-07155

Inspection: 700402272





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Infrared image of casing valve.

M.B. Larson C9X25

API: 05-103-07155

Inspection: 700402272