

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2020

Submitted Date:

07/01/2020

Document Number:

699302051**FIELD INSPECTION FORM**Loc ID 336264 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300532	WELL	SI	04/01/2020	OW	123-29742	DOLPH 1-1	SI
300545	WELL	SI	04/01/2020	OW	123-29753	DOLPH 9-1	SI
300546	WELL	SI	04/01/2020	GW	123-29754	DOLPH 41-1	SI
300547	WELL	SI	04/01/2020	OW	123-29755	DOLPH 26-1	SI
300548	WELL	SI	04/01/2020	OW	123-29756	DOLPH 24-1	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag fence x 5		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	all are exposed at surface		
Corrective Action:		Date:	
Type: Flow Line	# 2		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 10		
Comment:	automation		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card inside meter house indicates that calibration is current		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card inside meter house indicates that calibration is due (brown meter house)		
Corrective Action:	Comply with Rule 328/329 measurement of gas/oil	Date:	07/31/2020

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	shares containment with crude tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 300532 Type: WELL API Number: 123-29742 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 4-1-2020 Form 42(PR) Doc #402328236 submitted on 3-2-2020 and is approved

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 300545 Type: WELL API Number: 123-29753 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 4-1-2020 Form 42(PR) Doc #402328125 submitted on 3-2-2020 and is approved

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 300546 Type: WELL API Number: 123-29754 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 4-1-2020.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 300547 Type: WELL API Number: 123-29755 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 4-1-2020 Form 42(PR) Doc #402328181 submitted on 3-2-2020 and is approved

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 300548 Type: WELL API Number: 123-29756 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 4-1-2020 Form 42(PR) Doc #402328202 submitted on 3-2-2020 and is approved

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 7/1/2020 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Dolph UPRR 62N-66W at Location #336264 in Weld County Colorado.</p> <p>While there, I observed a multi well pad and tank battery.</p> <p>Dolph 1-1: SI since 4-1-2020 Form 42(PR) Doc #402328236 submitted on 3-2-2020 and is approved, Dolph 9-1: SI since 4-1-2020 Form 42(PR) Doc #402328125 submitted on 3-2-2020 and is approved, Dolph 41-1: SI since 4-1-2020, Dolph 26-1: SI since 4-1-2020 Form 42(PR) Doc #402328189 submitted on 3-2-2020 and is approved and Dolph 24-1: SI since 4-1-2020 Form 42(PR) Doc #402328202 submitted on 3-2-2020 and is approved,</p> <p>During this inspection the following compliance issue was observed:</p> <p>Rule 328/329 measurement of gas/oil: Card inside meter house indicates that calibration is due (brown meter house), CA date 7-31-2020 see photo 8.</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	07/01/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402436321	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5189211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5189211</a>
699302052	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5189204">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5189204</a>