

Inspection Photos

Operator: Logos Operating
API: 067-05512
Date: 7/6/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Surface owner equipment has been moved outside of project area and stored in the surrounding areas. Vegetation is comprised of a mix of desirable and undesirable species in a grazed condition, such as smooth brome and western wheatgrass, as well as weeds such as kochia and cheatgrass.



Photo 3. View of the western project area facing northward.



Photo 4. View of the reference area, comprised of rocky substrate with grazed vegetation such as smooth brome and western wheatgrass, as well as weeds such as kochia and cheatgrass.