

Sample Site Locations*

Eagle Operating, Rangely Field, Colorado

sample no.	latitude	longitude	description (see also Google Earth photo map)
BG-01	40.096447	-108.909140	background spl from NW of area in undisturbed soil at 4 ft depth
PH-01	40.095721	-108.908689	SW sample from large covered pit area NW of dual tanks
PH-02	40.095765	-108.908662	E sample from large covered pit area NW of dual tanks
PH-03	40.095801	-108.908702	N sample from large covered pit area NW of dual tanks
PH-04	40.095090	-108.907918	Sample from beneath excavation of area of pipeline leak
PH-05	40.096015	-108.907574	Sample from beneath bottom of covered pit adjacent to tank at Emerald 275
SP-01	40.095123	-108.907916	Composite sample from soil pile excavated from above pipeline spill

* soil samples collected by LT Environmental and analyzed by ALS Environmental