

# Inspection Photos

7/8/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312482

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312482



**Photo 1:** Photo taken from the south end of the Location, facing northwest. Photo shows overview of the Location and reclamation area.



**Photo 2:** Photo taken from the south end of the Location, facing northeast. Photo shows overview of the Location and reclamation area.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312482



**Photo 3:** Photo taken from the north end of the Location, facing southeast. Photo shows overview of the Location and reclamation area.



**Photo 4:** Photo taken from the north end of the Location, facing southwest. Photo shows overview of the Location and reclamation area.



**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC - 10456**  
**Location ID: 312482**



**Photo 5:** Photo taken from the north end of the Location, facing west. Photo shows overview of the Location and reclamation area.



**Photo 6:** Photo taken from the south end of the Location. Photo shows 1 of 2 signs remaining on the Location; Operator information on the sign incorrect. Sign either needs to be updated or removed.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312482



**Photo 7:** Photo taken from the Location entrance on the south end. Photo shows 1 of 2 signs remaining on the Location; Operator information on the sign incorrect. Sign either needs to be updated or removed.

**Photo 8:** Photo taken from the adjacent reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312482



**Photo 9:** Photo taken from the adjacent reference area.



**Photo 10:** Photo taken from the access road, south of the Location facing west.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312482



**Photo 11:** Photo taken from the access road, south of the Location facing northeast.



**Photo 12:** Photo taken from the access road, east of the Location, facing southwest.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312482



**Photo 13:** Figure provided by Caerus shows access road for which a 502.b SOVR to waive reclamation requirements has been submitted.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312482



**Photo 10:** USGS Aerial Imagery Dated 9/2/1980. Well was SPUD 4/4/1980. Photo shows the disturbance area of this Location ~ 5 months post drilling activities.

