



Reference Number: 20200620-18145929235
Form Name: V2 Compliance Follow Up Form
Submitter Name: Cole Nichols (colen@horizonenvservices.com) | colen@horizonenvservices.com
Submission Date: Jun 20, 2020 11:23:27 AM MDT
Location: 579 Confluence Ave, Durango, CO 81301, USA
 Jun 20, 2020 11:22:33 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name colen@horizonenvservices.com
Date Jun 19, 2020
Well Name PAN AMERICAN FEE GAS UNIT B 1
API Number 50670579600
Select State Colorado
Work type suit inspection
Action Complete Other

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

treated roadsides

Photo of third corrective action completed



**Completed work description of corrective
action 3**

treated noxious weeds

Photo of fourth corrective action completed



Completed work description

treated noxious weeds

Completed work description of corrective action 4

treated noxious weeds in reclamation area and on road right of way

Additional photos



Additional photos



Completed work description

treated noxious weeds

Summary of all work completed

previous treatment dates 6/23/16, 7/21/17,
6/24/18, 6/26/19