

BP L48 San Juan



## V2 Compliance Follow Up Form

18146214348

**Reference Number:**

**Form Name:**

**Submitter Name:**

**Submission Date:**

**Location:**

20200623-18146214348

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Jun 23, 2020 10:34:39 AM MDT

577 Hillcrest Rd, Bayfield, CO 81122, USA

Jun 23, 2020 10:31:55 AM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

<b>Name</b>	kenneth.canterbury@crossfire-llc.com
<b>Date</b>	Jun 19, 2020
<b>Well Name</b>	GEARHART GAS UNIT 01-32 FT 1
<b>API Number</b>	50670654600
<b>Select State</b>	Colorado
<b>Work type</b>	COGCC Inspection AR
<b>Action Complete</b>	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils

**Photo of first corrective action completed**



Completed work description Corrective  
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective action 2**

Picked up operators equipment

**Photo of third corrective action completed**





**Completed work description of corrective  
action 3**

Fixed erosion

**Photo of fourth corrective action completed**



**Completed work description**

Installed rock run down

**Completed work description of corrective action 4**

Cleaned up stains

**Additional photos**



**Summary of all work completed**

Compliance, fixed erosion , installed rock run down , picked up operators equipment and cleaned up stains