

BP L48 San Juan



## V2 Compliance Follow Up Form

18146746581

**Reference Number:**

20200629-18146746581

**Form Name:**

V2 Compliance Follow Up Form

**Submitter Name:**

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

**Submission Date:**

Jun 29, 2020 11:48:36 AM MDT

**Location:**

1916-1922 N La Boca Canyon Rd, Ignacio, CO 81137, USA

Jun 29, 2020 11:45:41 AM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

<b>Name</b>	kenneth.canterbury@crossfire-llc.com
<b>Date</b>	Jun 23, 2020
<b>Well Name</b>	KNIGHT GAS UNIT C 2
<b>API Number</b>	50670874500
<b>Select State</b>	Colorado
<b>Work type</b>	COGCC Inspection AR
<b>Action Complete</b>	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils

**Photo of first corrective action completed**



Completed work description Corrective Action 1 Compliance  
Photo of second corrective action completed



**Completed work description of corrective action 2**

Installed diversion ditch

**Photo of third corrective action completed**



**Completed work description of corrective action 3**

Cleaned up stains

**Photo of fourth corrective action completed**



**Completed work description**

Fixed erosion

**Completed work description of corrective action 4**

Installed rock run down

**Additional photos**

**Completed work description**

Installed diversion ditch along cut slope, cleaned up stains by the day tank , installed rock run down, fixed erosion and cleaned up trash on location.

**Summary of all work completed**

Installed diversion ditch, cleaned up stains , fixed erosion , installed rock run down and picked up trash.