



<b>Reference Number:</b>	20200707-18147562260
<b>Form Name:</b>	V2 Compliance Follow Up Form
<b>Submitter Name:</b>	Cole Nichols (colen@horizonenvservices.com)   colen@horizonenvservices.com
<b>Submission Date:</b>	Jul 7, 2020 4:45:39 PM MDT
<b>Location:</b>	557 Airpark Dr, Durango, CO 81303, USA Jul 7, 2020 4:44:46 PM MDT [ <a href="#">View Map</a> ]

## INFORMATION

### Section 1

<b>Name</b>	colen@horizonenvservices.com
<b>Date</b>	Jun 25, 2020
<b>Well Name</b>	SNOOK GAS UNIT C 1
<b>API Number</b>	50670784300
<b>Select State</b>	Colorado
<b>Work type</b>	COGCC Inspection AR
<b>Action Complete</b>	Compliance Inspection Actions Seeding Clean Up Weed Debris

Photo of first corrective action completed



<b>Completed work description</b>	Corrective	blanket slopes
<b>Action 1</b>		

Photo of second corrective action completed



**Completed work description of corrective action 2** blanket slopes

**Photo of third corrective action completed**



**Completed work description of corrective action 3** blanket slopes

**Photo of fourth corrective action completed**



**Completed work description**

clean up debris

**Completed work description of corrective action 4**

cleaned up debris

**Summary of all work completed**

seeded and blanket the slopes. cleaned up debris.