

BP L48 San Juan



V2 Compliance Follow Up Form

18147851380

Reference Number:

20200710-18147851380

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Submission Date:

Jul 10, 2020 12:01:12 PM MDT

Location:

91 S Skylane Dr, Durango, CO 81303, USA

Jul 10, 2020 12:04:02 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 8, 2020

Well Name

MOSKETTI GAS UNIT 43-33 1

Location Name (Other)

mosketti 43-33 3

API Number

50670777700

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

treated noxious weeds


Photo of third corrective action completed



Completed work description of corrective action 3

removed vegetation around equipment

Photo of fourth corrective action completed



Completed work description

removed vegetation from around equipment

Completed work description of corrective action 4

removed vegetation from around equipment, treated noxious weeds, removed seedheads

Additional photos



Additional photos

**Completed work description**

removed vegetation from around equipment,
treated noxious weeds and removed seedheads

Summary of all work completed

previous treatment dates 7/7/16, 7/6/17, 7/3/18,
7/1/19