

Inspection Photos
Location Name: WPF III-66N64W /18SWSW
Location #: 332855



Photo #1

Log Cabin #1 (05-123-13426) Wellsite
Plugged & Abandoned | PA
~ 10 yds.
Unused Equipment on site



Photo #2

Log Cabin #1 Battery site
Abandoned: ALL Equipment Removed

Inspection Photos
Location Name: WPF III-66N64W /18SWSW
Location #: 332855



Photo #3
Log Cabin #1 Wellsite
Plugged & Abandoned | PA
Unused Equipment on site:
Electrical Panel



Photo #4
Log Cabin #1 Wellsite
Plugged & Abandoned | PA
Unused Equipment on site:
Road Drag

Inspection Photos

Location Name: WPF III-66N64W /18SWSW

Location #: 332855



Photo #5

Log Cabin #1 Wellsite

Plugged & Abandoned | PA

Unused Equipment on site:

Deadman anchor, SE of wellsite



Photo #6

Log Cabin #1 Wellsite

Plugged & Abandoned | PA

Unused Equipment on site:

Deadman anchor, SW of wellsite