

**Inspection Photos**  
**Location Name: IGS #405**  
**API: 05-067-09073**



**IGS #405 production equipment. Hoses and pipe fittings not in use observed near meter run and separator.**



**IGS #405 well head.**

**Inspection Photos**  
**Location Name: IGS #405**  
**API: 05-067-09073**



**300 bbl. steel AST with fenced earthen berm.**



**View from location entrance along western edge of location.**