

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402443013

Date Received:
07/14/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Doug Dennison</u>	<u>970-353-0407</u>	<u>ddennison@hpres.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901838
Inspection Date: 05/27/2020 FIR Submit Date: 05/29/2020 FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 322139

Location Name: NEELY-N39N17W Number: 7SWSW County: DOLORES
Qtrqr: SWS Sec: 7 Twp: 39N Range: 17W Meridian: N
Latitude: 37.646850 Longitude: -108.771510

FACILITY - API Number: 05-033-00 Facility ID: 297621

Facility Name: NEELY Number: 13H-7-39-17
Qtrqr: SWS Sec: 7 Twp: 39N Range: 17W Meridian: N
Latitude: 37.646850 Longitude: -108.771510

CORRECTIVE ACTIONS:

1 CA# 139393

Corrective Action:

Date: 06/30/2020

-Conduct soil sampling to determine the likely cause of poor revegetation. As described below, results shall be submitted with a remediation/reclamation plan for the project area.

-Submit a plan to remediate and reclaim the project area. Plan needs to include at a minimum, the following:

- Copies of any soil testing results from testing that was previously conducted at the location.
- Soil sample results from 2020 soil sampling.
- A detailed soil remediation and reclamation plan based on soil sampling results.
- Schedule to conduct soil remediation activities and reclamation activities in coordination with surface owner and crop timing at all phases of remediation/reclamation.
- A soil sampling/remediation map.

Response: CA COMPLETED

Date of Completion: 06/09/2020

Operator Comment: HighPoint Resources' reclamation consultant performed periodic monitoring of this location in June, 2020, and a report of their findings is included with this response. The consultant collected soil samples from both the project area and an adjacent undisturbed area, and the results are provided in the included report. Results from soil samples taken previously at this location are also included. Based on their observations and the results for the soil samples, the consultant is recommending reseeding the bare areas in spring 2021 and preceding the reseeding with the application of Nitrogen and Phosphate. Based on observations from monitoring to be conducted in the fall of 2020 a spring 2021 foliar treatment of copper may also be required. All treatments and other future work will be coordinated with and approved by the landowner and/or tenant farmer. Regular monitoring of reclamation success will continue until such time the reclaimed area meets the 1004 reclamation standards.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachments for sote specific information.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Doug Dennison

Signed: _____

Title: Dir. Community Affairs

Date: 7/14/2020 12:18:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402443020	Soil Recommendations
402443025	Onsite soils 2020
402443026	Offsite soils 2020
402443027	2019 Soil Data

Total Attach: 4 Files