

# Final Reclamation Inspection

July 13, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 302242

Inspection Document #: 697501748

Weld County, CO

NWNW Section 20 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Larson 20-52  
Location ID: 302242



**Photo 1.** Photo taken west of the location, facing East. Photo illustrates location was not constructed at the proposed well location based off field observations.