

# Interim Reclamation and Stormwater Inspection

July 13, 2020

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 430703

Inspection Document #: 697501754

Weld County, CO

NENE Section 26 T7N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Google Earth aerial imagery taken 7/17/2019. The red polygon areas currently have weeds. The orange circles wells have been plugged; therefore, the Operator will likely have to perform interim reclamation to reduce all areas not needed for production operations.

Inspection Photos  
Location Name: Casa Loma /4-25  
Location ID: 430703



**Photo 2.** Photo taken from the northern location, facing Northeast. Photo illustrates an area that was previously the original access entrance before the adjacent Lind location was built. This area has unmanaged Kochia weeds.



Inspection Photos  
Location Name: Casa Loma /4-25  
Location ID: 430703



**Photo 3.** Photo taken from the northeastern location, facing South. Photo illustrates an area where wells have been plugged. Operator will likely have to perform interim reclamation to reduce all areas not needed for production operations.

Inspection Photos  
Location Name: Casa Loma /4-25  
Location ID: 430703



**Photo 4.** Photo taken from the entrance of location, facing West. Photo illustrates unmanaged Kochia weeds. It is unclear whether this location is associated with the adjacent Lind location to the west or whether this is from this location.