



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Universal 2-19

API: 05-103-07923

Inspection: 700402384



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Universal 2-19

API: 05-103-07923

Inspection: 700402384







COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tubing valve gas leak.

Universal 2-19

API: 05-103-07923

Inspection: 700402384