

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2020

Submitted Date:

07/15/2020

Document Number:

690006202**FIELD INSPECTION FORM**
 Loc ID 461939 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
462891	WELL	XX	03/03/2019		123-49854	BERRY IC 11-039HN	ND
462892	WELL	XX	03/03/2019		123-49855	BERRY IC 11-202HN	ND
462893	WELL	XX	03/03/2019		123-49856	BERRY IC 11-119HN	ND
462895	WELL	XX	03/03/2019		123-49858	BERRY IC 11-039HC	ND
462896	WELL	XX	03/03/2019		123-49859	BERRY IC 11-239HN	ND
462897	WELL	XX	03/03/2019		123-49860	BERRY IC 11-239HNX	ND
462900	WELL	XX	03/03/2019		123-49863	BERRY IC 11-119HNX	ND
462901	WELL	XX	03/03/2019		123-49864	BERRY IC 11-082HC	ND
462902	WELL	XX	03/03/2019		123-49865	BERRY IC 11-042HN	ND
462903	WELL	XX	03/03/2019		123-49866	BERRY IC 11-162HNX	ND
462904	WELL	XX	03/03/2019		123-49867	BERRY IC 11-159HN	ND
462905	WELL	XX	03/03/2019		123-49868	BERRY IC 11-042HNX	ND
463045	WELL	XX	03/05/2019		123-49915	BERRY IC 11-162HN	ND

General Comment:

Inspected Facilities				
Facility ID: <u>462891</u>	Type: <u>WELL</u>	API Number: <u>123-49854</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462892</u>	Type: <u>WELL</u>	API Number: <u>123-49855</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462893</u>	Type: <u>WELL</u>	API Number: <u>123-49856</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462895</u>	Type: <u>WELL</u>	API Number: <u>123-49858</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462896</u>	Type: <u>WELL</u>	API Number: <u>123-49859</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462897</u>	Type: <u>WELL</u>	API Number: <u>123-49860</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462900</u>	Type: <u>WELL</u>	API Number: <u>123-49863</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462901</u>	Type: <u>WELL</u>	API Number: <u>123-49864</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462902</u>	Type: <u>WELL</u>	API Number: <u>123-49865</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462903</u>	Type: <u>WELL</u>	API Number: <u>123-49866</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462904</u>	Type: <u>WELL</u>	API Number: <u>123-49867</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>462905</u>	Type: <u>WELL</u>	API Number: <u>123-49868</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>463045</u>	Type: <u>WELL</u>	API Number: <u>123-49915</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

COGCC Comments		
Comment	User	Date
Wells associated with this inspection are status XX and have not been drilled. Battey and drilling pad is under construction at time of inspection. Two active wells are on the location and have a separate inspection, these wells are shown in the attached photos.	carlilec	07/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690006203	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5196738