

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402444089

Date Received:

07/15/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 39560

Name of Operator: TOP OPERATING COMPANY

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Paul Herring</u>	<u>7206631698</u>	<u>paul.herring@topoperating.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689501048

Inspection Date: 05/19/2020

FIR Submit Date: 05/19/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TOP OPERATING COMPANY

Company Number: 39560

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: NENW Sec: 31 Twp: 3N Range: 68W Meridian: 6

Latitude: 40.187067 Longitude: -105.048726

FACILITY - API Number: 05-123- -00 Facility ID: 476473

Facility Name: Produced Water Vessel Number: _____

Qtrqr: NENW Sec: 31 Twp: 3N Range: 68W Meridian: 6

Latitude: 40.187067 Longitude: -105.048726

CORRECTIVE ACTIONS:

1 CA# 139163

Corrective Action: Upon completion of soil excavation Operator shall submit a Supplemental Form 27 including confirmation soil sample results, waste manifests for removal of impacted material (soil and groundwater), and a plan for full delineation of groundwater impacts and continued groundwater monitoring.

Date: 07/03/2020

Response: CA COMPLETED

Date of Completion: 07/14/2020

Operator Comment: Per the Initial Form 27 (doc #402398543), approved by the COGCC on May 14, 2020, a COA stated "Operator shall submit a Form 27 Supplemental Report within 45 days of performing this environmental investigation." The final soil samples collected as part of this environmental investigation were collected on June 30, 2020. The final lab results were received on July 1, 2020.

A supplemental form 27 (doc id. 402443140) was submitted.

A supplemental form 27 will be submitted to the COGCC by August 7, 2020 outlining proposed monitoring well installation activities, proposed soil and groundwater sampling plans, details of cubic yards of soil removed during excavation activities, and details of groundwater removed during excavation activities.

Attached is Eagle Environmental's timeline, which does not include updates provided by TOP to the City of Longmont via email and phone, as well as co-sampling events TOP facilitated with Terracon, the City of Longmont's environmental consultant.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Per the Initial Form 27 (doc #402398543), approved by the COGCC on May 14, 2020, a COA stated "Operator shall submit a Form 27 Supplemental Report within 45 days of performing this environmental investigation."

Attached is Eagle Environmental's timeline, which does not include updates provided by TOP to the City of Longmont via email and phone, as well as co-sampling events TOP facilitated with the City.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: _____

Title: Landman

Date: 7/15/2020 4:20:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402444404	Eagle environmental timeline

Total Attach: 1 Files