

Inspection Photos

API: 073-06509

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 7/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 1. Facing north along the former access road. It appears a two track road exists along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 2. Facing north along the form access road. This is where the road splits to go to the two separate well sites. The vegetation has not established in this area. It appears soil may be compacted in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 3. Facing southwest along the access road to the location. The vegetation has not established in this area. It appears soil may be compacted in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 4. Facing south at the location. Vegetation has not adequately established and there are areas of the location that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 5. Facing southwest at the location. There is sparse vegetation at the location compared to outside of the location. Most of the vegetation is a Bunch grass growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 6. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 7. Facing north at the location. Vegetation has not adequately established and there are areas of the location that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 8. This photo shows a comparison of the reference area on the left side of photo and the disturbed location on right.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020

Inspection Photos



Photo 9. Facing northeast toward the surrounding rangeland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06509 | Date: 7/14/2020