

# Inspection Photos

API: 073-06510

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 7/14/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020

## Inspection Photos



**Photo 1.** Facing south at the beginning of the access road. The access road is bare of vegetation along the majority of the road to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020

## Inspection Photos



**Photo 2.** Facing south along the access road. The access road is bare of vegetation along the majority of the road to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020



## Inspection Photos



**Photo 3.** Facing south along the former road near the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020

## Inspection Photos



**Photo 4.** Facing south at the location. The location is bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020



## Inspection Photos



**Photo 5.** Facing east at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020

## Inspection Photos



**Photo 6.** Southwest corner facing northeast. The location is bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020



## Inspection Photos



**Photo 7.** South side of the location facing north.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020



## Inspection Photos



**Photo 8.** This photo shows a comparison of the undisturbed reference area on the right side of photo and the disturbed location on the left side.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020

## Inspection Photos



**Photo 9.** Southeast side of the location facing northwest.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020



## Inspection Photos



**Photo 10.** Facing southeast toward the surrounding rangeland.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06510 | Date: 7/14/2020