

Inspection Photos

Operator: Paradox Upstream
API: 113-06099
Date: 7/14/2020



Photo 1. View of the project area from the northwestern corner facing center. Dense kochia growing on the well pad.



Photo 2. View of the northern fill slope, facing westward, comprised of grasses and weeds such as western wheatgrass, crested wheatgrass, and cheatgrass.



Photo 3. View of the eastern project area from the northeaster corner facing southward.



Photo 4. View of reference area comprised of black sage shrubland with needle and thread grass, blue grama, snakeweed, and sand heath.