

Inspection Photos
Operator: Paradox Upstream
API: 113-06151
Date: 7/14/2020



Photo 1. View of the project area from the northwestern corner facing center. Dense kochia growing on the well pad.



Photo 2. View of the western reclamation area from the northwestern corner facing southward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, and fourwing saltbush.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of black sage shrubland with needle and thread grass, blue grama, snakeweed, and sand heath.