

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621



Photo 3: Wellhead fencing damaged



Photo 4: Weeds

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621




Photo 5: Tank Battery Sign



Photo 6: Tank Battery

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621



Photo 7: Weeds on location



Photo 8: Hole in berm

Inspection Photos
Location Name: Kettler 1-18
Location ID: 322621



Photo 9: Hole in bem