

# Inspection Photos

Operator: Paradox Upstream  
API: 113-06229  
Date: 7/15/2020



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, rubber rabbitbrush, largely in a grazed vegetative condition.





Photo 3. View of musk thistles within the western project area. Approximately 75 individuals observed.





Photo 4. View of reference area comprised of big sagebrush shrubland with scattered pinyon and juniper trees and grassy understory of blue grama and western wheatgrass.